



Thank you for choosing to purchase a genuine North Georgia Copper Still! Your still has been hand crafted by the best Coppersmiths in the industry. It has also been hand washed and allowed to air dry. This process of air drying is the best way to dry your still, but sometimes leaves small water spots behind. These water spots are easy to clean with a little polish. Additionally, sometimes a little water gets in the still pot as we hand wash them and leaves a green residue as it dries. This is normal when water dries on copper and is not harmful to you in any way. As you follow the below cleaning directions to get your still ready for your first of many runs the pot and accessories will become thoroughly cleaned. You will need to do a little prep work to get your beauty set up and ready for action. You will need the following:

- White Vinegar
 - Salt
 - Gloves
- Dish Brush OR New Toilet Brush

CLEANING:

Before the first use of your still, we recommend washing the inside with a salt and vinegar mixture: ½ cup of salt and 1 gallon of vinegar. Heat the vinegar to about 110-115 degrees. Pour your mixture into your equipment. Using your brush, scrub the inside of your pot and cap. Then, pour the mixture into your worm and thumper and clean those as well. Once all equipment has been cleaned, rinse everything with fresh water. Repeat as necessary. After the initial cleaning, you'll want to do a "cleaning run" (once your set-up is complete), by distilling fresh water with 1 cup of vinegar per 5 gallons of water to help clean the lines. Do not run cold water to the worm, to allow vapor to clean coil during cleaning run. Remember to rinse everything with fresh water when done.